

Contact: Eric Mayne
Berj Alexanian

Statement: Wire Harness Crimp

July 22, 2016, Auburn Hills, Mich. - FCA US LLC is voluntarily recalling an estimated 323,361 vehicles in the U.S. to update certain software and replace wire harnesses, as needed.

An examination of warranty data led to an FCA US investigation that discovered an insufficient crimp in a wire harness. Such a crimp may lead to a solenoid fault code that can cause propulsion loss.

The Company is unaware of any related injuries or accidents.

Most vehicles in the recall population will not experience this fault code over their lifetimes. However, should the condition occur, it can typically be temporarily resolved by stopping the vehicle and re-starting its engine.

Accordingly, FCA US urges customers to heed the instructions on their recall notices.

Affected are certain model-year 2015 Chrysler 200 midsize sedans, Ram ProMaster City small vans, Jeep Renegade and Cherokee SUVs. Certain model-year 2014 Cherokees are also affected.

A change made in the harness-manufacturing process eliminates the need to recall any vehicle built after Sept. 23, 2014.

An estimated 35,511 additional vehicles in Canada are included in the campaign; as are 7,067 in Mexico; and 43,927 outside the NAFTA region.

Customers will be advised when they may schedule service. Those with questions may call the FCA US Customer Care Center at 1-800-853-1403.

-###-

Additional information and news from Stellantis are available at: <https://media.stellantisnorthamerica.com>